

Oil Field Environmental Incident Summary

Incident: 20150612131215 **Date/Time of Notice:** 06/12/2015 13:12

Responsible Party: SLAWSON EXPLORATION COMPANY, INC.

Well Operator: SLAWSON EXPLORATION COMPANY, INC.

Well Name: VAGABOND 1-27H

Field Name: VAN HOOK

Well File #: 19207

Date Incident: 6/11/2015 **Time Incident:** 19:15

Facility ID Number:

County: MOUNTRAIL

Twp: 151

Rng: 92

Sec: 27

Qtr: SE SW

Location Description:

Submitted By: Ray Gorka

Received By:

Contact Person: Ray Gorka
1675 BROADWAY STE 1600
DENVER, CO 80202

General Land Use: Cultivated

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 8200 Feet

Distance Nearest Water Well: 8200 Feet

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	32	Barrels	31.5	Barrels	32	barrels

Brine

Other

Description of Other Released Contaminant:

.....

Inspected:

Written Report Received: 4/11/2016

Clean Up Concluded: 6/12/2015

Risk Evaluation:

none....

Areal Extent:

.....

Potential Environmental Impacts:

none.....

Action Taken or Planned:

Better SPCC inspections..

Wastes Disposal Location: Licensed disposal facility.

Agencies Involved:

Updates

Date: 6/15/2015 **Status:** Reviewed - Assigned to Other Agency **Author:** Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.